

Inspection Photos
Location Name: Walsh #2
Location ID: 318151



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Walsh #2
Location ID: 318151



Photo 3 ECD, Gas meter run & Heated horiz. Sep.



Photo 4 Compressor belt guard is removed

Inspection Photos
Location Name: Walsh #2
Location ID: 318151



Photo 5 unused comp.belt



Photo 6 Tank has no label/placard or volume of contents

Inspection Photos
Location Name: Walsh #2
Location ID: 318151



Photo 7 Tank has no label/placard or volume of contents



Photo 8 unused unmarked flow line riser no LOTO

Inspection Photos
Location Name: Walsh #2
Location ID: 318151



Photo 9 Compressor sign



Photo 10 TB sign



Inspection Photos
Location Name: Walsh #2
Location ID: 318151



Photo 11 TB paint chipping



Photo 12 TB