

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/08/2020

Submitted Date:

01/08/2020

Document Number:

699100867

FIELD INSPECTION FORM

Loc ID 306539 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289544	WELL	PR	06/12/2007	OW	123-24872	CONNELL C 4-29	TA

General Comment:

[This is a follow up to prior inspection document #699100645. CA has been corrected.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 289544 Type: WELL API Number: 123-24872 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 1/8/20 at approximately 0830 hrs, I, Inspector Adam Burns, Conducted a follow up inspection to prior document #699100645 at Connell C 4-29 of Noble Energy, at API # 05-123-24872 in Weld County, Colorado. During this inspection the compliance issues were corrected. See attached photo This is a summary of inspection report. Continuing education inspections</p>	burnsa	01/08/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699100868	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030892