

Inspection Photos
Operator: BP America
Location/API #: 067-07328
Date: 1-6-2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Residential housing and storage located near the project area, but not within the project area. Revegetation is progressing with grasses such as smooth brome and intermediate wheatgrass.



Photo 3. View of the southern project area from the southeastern corner facing westward. Dense weed debris from mustards and kochia observed near the well pad entrance and in the southeastern interim reclamation area.



Photo 4. View of reference area, comprised of irrigated grass field largely comprised of smooth brome.