

Inspection Photos
location 428531
Remediation Projects 14686 & 10268
Inspection Date: 1/7/2020
Photos taken by Kris Neidel



Photo #1 Drilling a groundwater observation well on the north side of old cuttings pit.



Inspection Photos
location 428531
Remediation Projects 14686 & 10268
Inspection Date: 1/7/2020
Photos taken by Kris Neidel



Photo #2 location of monitoring well. Note main tank battery in back. Construction fence is to prevent access to old soil storage area.

