

Inspection Photos

location 428531

Remediation Projects 14686 & 10268

Inspection Date: 1/7/2020

Photos taken by Kris Neidel



Photo #1 Completed well on north side of old soil storage pit.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos

location 428531

Remediation Projects 14686 & 10268

Inspection Date: 1/7/2020

Photos taken by Kris Neidel



Photo #2 measuring groundwater depth on west side of old soil storage pit. Note: shop and pump building in background for reference.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos

location 428531

Remediation Projects 14686 & 10268

Inspection Date: 1/7/2020

Photos taken by Kris Neidel



Photo #3 monitoring well install on west side of old cuttings storage pit. Note: production tanks in background.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources