

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2020

Submitted Date:

03/02/2020

Document Number:

689704281**FIELD INSPECTION FORM**Loc ID 335699 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287610	WELL	TA	09/01/2018	GW	045-13007	N. PARACHUTE CP14A-09 G09 59	TA
287621	WELL	SI	08/01/2018	GW	045-13006	N. PARACHUTE CP07B-09 G09 59	TA
287624	WELL	TA	09/01/2018	GW	045-13004	N. PARACHUTE CP02D-09 G09 59	TA
291109	WELL	TA	12/01/2018	GW	045-14297	N.PARACHUTE CP11B-09 G09 596	TA
454313	WELL	XX	03/14/2018		045-23860	NPR 12C-9-596	ND
454314	WELL	XX	03/14/2018		045-23861	NPR 21B-9-596	ND
454315	WELL	XX	03/14/2018		045-23862	NPR 22B-9-596	ND
454316	WELL	XX	03/14/2018		045-23863	NPR 22D-9-596	ND
454317	WELL	XX	03/14/2018		045-23864	NPR 14B-9-596	ND
454318	WELL	XX	03/14/2018		045-23865	NPR 21C-9-596	ND
454319	WELL	XX	03/14/2018		045-23866	NPR 11B-9-596	ND
454320	WELL	XX	03/14/2018		045-23867	NPR 12D-9-596	ND
454321	WELL	XX	03/14/2018		045-23868	NPR 12B-9-596	ND
454322	WELL	XX	03/14/2018		045-23869	NPR 13D-9-596	ND
454323	WELL	XX	03/14/2018		045-23870	NPR 14C-9-596	ND
454324	WELL	XX	03/14/2018		045-23871	NPR 13A-9-596	ND
454325	WELL	XX	03/14/2018		045-23872	NPR 22A-9-596	ND
454326	WELL	PR	05/01/2019		045-23873	NPR 11C-9-596	PR

454327	WELL	PR	05/01/2019		045-23874	NPR 11D-9-596	SI
454328	WELL	XX	03/14/2018		045-23875	NPR 13B-9-596	ND
454329	WELL	PR	08/01/2019		045-23876	NPR 11A-9-596	SI
454330	WELL	DG	02/18/2019		045-23877	NPR 21A-9-596	DG
454331	WELL	PR	05/01/2019		045-23878	NPR 12A-9-596	PR
454332	WELL	XX	03/14/2018		045-23879	NPR 24A-9-596	ND
454333	WELL	XX	03/14/2018		045-23880	NPR 23B-9-596	ND
454334	WELL	PR	05/01/2019		045-23881	NPR 25D-4-596	PR
454335	WELL	XX	03/14/2018		045-23882	NPR 23D-9-596	ND
454336	WELL	XX	03/14/2018		045-23883	NPR 23C-9-596	ND
454337	WELL	XX	03/14/2018		045-23884	NPR 23A-9-596	ND
454338	WELL	XX	03/14/2018		045-23885	NPR 24B-9-596	ND
454339	WELL	DG	01/28/2019		045-23886	NPR 25C-4-596	TA
454353	WELL	XX	03/15/2018		045-23887	NPR 14A-9-596	ND

**General Comment:**

This is a summary of inspection report.

On Friday 02/28/2020, I, Inspector Mike Longworth, conducted a field inspection at CAERUS PICEANCE LLC NPR G09 Pad, at Location # 335699 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

No labels on tanks.

No well signs on 11D-9 and 12A-9

Unused/unneeded equipment. 2-500 bbl frac tanks.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No well signs on 11D-9 and 12A-9		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	05/02/2020
Type	TANK LABELS/PLACARDS		
Comment:	No labels on tanks.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	05/02/2020

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused/unneeded equipment. 2-500 bbl frac tanks.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/02/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	2	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other				
Comment:	No berm around tanks.			
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	287610	Type:	WELL	API Number: 045-13007 Status: TA Insp. Status: TA
Facility ID:	287621	Type:	WELL	API Number: 045-13006 Status: SI Insp. Status: TA
Facility ID:	287624	Type:	WELL	API Number: 045-13004 Status: TA Insp. Status: TA
Facility ID:	291109	Type:	WELL	API Number: 045-14297 Status: TA Insp. Status: TA
Facility ID:	454313	Type:	WELL	API Number: 045-23860 Status: XX Insp. Status: ND
Facility ID:	454314	Type:	WELL	API Number: 045-23861 Status: XX Insp. Status: ND
Facility ID:	454315	Type:	WELL	API Number: 045-23862 Status: XX Insp. Status: ND
Facility ID:	454316	Type:	WELL	API Number: 045-23863 Status: XX Insp. Status: ND
Facility ID:	454317	Type:	WELL	API Number: 045-23864 Status: XX Insp. Status: ND
Facility ID:	454318	Type:	WELL	API Number: 045-23865 Status: XX Insp. Status: ND
Facility ID:	454319	Type:	WELL	API Number: 045-23866 Status: XX Insp. Status: ND
Facility ID:	454320	Type:	WELL	API Number: 045-23867 Status: XX Insp. Status: ND
Facility ID:	454321	Type:	WELL	API Number: 045-23868 Status: XX Insp. Status: ND
Facility ID:	454322	Type:	WELL	API Number: 045-23869 Status: XX Insp. Status: ND
Facility ID:	454323	Type:	WELL	API Number: 045-23870 Status: XX Insp. Status: ND
Facility ID:	454324	Type:	WELL	API Number: 045-23871 Status: XX Insp. Status: ND
Facility ID:	454325	Type:	WELL	API Number: 045-23872 Status: XX Insp. Status: ND
Facility ID:	454326	Type:	WELL	API Number: 045-23873 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:

Facility ID:	454327	Type:	WELL	API Number:	045-23874	Status:	PR	Insp. Status:	SI
<b>Idle Well</b>									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____									
Comment: <input style="width: 50%;" type="text"/>									
Corrective Action: <input style="width: 50%;" type="text"/> Date: _____									
Facility ID:	454328	Type:	WELL	API Number:	045-23875	Status:	XX	Insp. Status:	ND
Facility ID:	454329	Type:	WELL	API Number:	045-23876	Status:	PR	Insp. Status:	SI
<b>Idle Well</b>									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____									
Comment: <input style="width: 50%;" type="text"/>									
Corrective Action: <input style="width: 50%;" type="text"/> Date: _____									
Facility ID:	454330	Type:	WELL	API Number:	045-23877	Status:	DG	Insp. Status:	DG
<b>Idle Well</b>									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____									
Comment: <input style="width: 50%;" type="text"/> <span style="color: blue;">Cellar covered with snow. No visual of well.</span>									
Corrective Action: <input style="width: 50%;" type="text"/> Date: _____									
Facility ID:	454331	Type:	WELL	API Number:	045-23878	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment: <input style="width: 50%;" type="text"/> <span style="color: blue;">Producing well</span>									
Corrective Action: <input style="width: 50%;" type="text"/> Date: <input style="width: 10%;" type="text"/>									
Facility ID:	454332	Type:	WELL	API Number:	045-23879	Status:	XX	Insp. Status:	ND
Facility ID:	454333	Type:	WELL	API Number:	045-23880	Status:	XX	Insp. Status:	ND
Facility ID:	454334	Type:	WELL	API Number:	045-23881	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment: <input style="width: 50%;" type="text"/> <span style="color: blue;">Producing well</span>									
Corrective Action: <input style="width: 50%;" type="text"/> Date: <input style="width: 10%;" type="text"/>									
Facility ID:	454335	Type:	WELL	API Number:	045-23882	Status:	XX	Insp. Status:	ND
Facility ID:	454336	Type:	WELL	API Number:	045-23883	Status:	XX	Insp. Status:	ND
Facility ID:	454337	Type:	WELL	API Number:	045-23884	Status:	XX	Insp. Status:	ND

Facility ID:	454338	Type:	WELL	API Number:	045-23885	Status:	XX	Insp. Status:	ND
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Facility ID:	454339	Type:	WELL	API Number:	045-23886	Status:	DG	Insp. Status:	TA
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: 4/29/2019 Form 42 NOTICE OF HYDRAULIC FRACTURING TREATMENT doc# 402024697. Well has frac valve on it.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID:	454353	Type:	WELL	API Number:	045-23887	Status:	XX	Insp. Status:	ND
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited BMP inspection due to snow cover.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402329138	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082791">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082791</a>
689704285	Inspection 689704281 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082781">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5082781</a>