

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Mitchell /32-6 Pad

Location ID: 334551



Photo #0732 from entrance to location



Photo #0733 Unused 2" piping by separators.



## Inspection Photos

Location Name: LARAMIE ENERGY LLC Mitchell /32-6 Pad

Location ID: 334551



**Photo #0734 Multiple holes through out tank containment liner.**



**Photo #0735 Multiple holes through out tank containment liner.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Mitchell /32-6 Pad

Location ID: 334551



**Photo #0736 Multiple holes through out tank containment liner.**