

Inspection Photos
Location Name: Antelope P-29 PAD
Location ID: 428984



Photo 1 – Wells



Photo 2 – Separators

Inspection Photos
Location Name: Antelope P-29 PAD
Location ID: 428984



Photo 3 – Tank Battery



Photo 4 – Unused Pipe fittings at Maintenance Tank. Please replace Cover on Tank

Inspection Photos
Location Name: Antelope P-29 PAD
Location ID: 428984




Photo 5 – Unmarked Risers




Photo 6 – Unmarked Risers

Inspection Photos
Location Name: Antelope P-29 PAD
Location ID: 428984




Photo 7 – Unmarked Risers