

**Inspection Photos**  
**Location Name: State Antelope T-28 PAD**  
**Location ID: 431935**




**Photo 1 – Wells**




**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: State Antelope T-28 PAD**  
**Location ID: 431935**



**Photo 3 – Unmarked Risers**



**Photo 4 – Stained Soil and Unused Rod**