

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/02/2020

Submitted Date:

03/11/2020

Document Number:

688000396

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10330  
Name of Operator: INVESTMENT EQUIPMENT LLC  
Address: 412 W PLATTE AVE  
City: FT MORGAN State: CO Zip: 80701

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Chisholm, Jim	405-642-9437	investmentequipment@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
472892	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

**General Comment:**

[Environmental inspection related to Spill ID 472892. GPS map of spill area and spill location photographs attached.](#)

**Inspected Facilities**

Facility ID: 472892 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: 10

Comment: Spill caused by animal burrow in the produced water pit berm.

Corrective Action: From Spill Reports COA "Collect a minimum of four soil samples from the spill affected area and one nonimpacted (background) sample for laboratory analysis of pH, EC and SAR for comparison to Table 910-1 allowable concentrations. Two samples should be from the first area along the flowpath that the water spread out and covered a wide area of winter wheat". Submit the analytical results and soil sample location map on a supplemental Form 19. Date: 03/31/2020

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402340252	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5093419">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5093419</a>
688000397	Spill outline map	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5093409">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5093409</a>
688000398	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5093410">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5093410</a>