

Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 1. Overview of workover on location taken facing north.



Photo 2. Tracking off of location onto Highway 14 facing south.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Gregory 0780 S9 Pad
Location ID: 439603



Photo 3. Tracking off of location onto Highway 14 facing north.



Photo 4. No tracking pad at entrance to location. Photo facing east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources