

A.C. McLaughlin 75X  
API: 05-103-08298  
Inspection: 700400604



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 1. Location.



A.C. McLaughlin 75X  
API: 05-103-08298  
Inspection: 700400604

deadman



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Fallen deadman in SW corner of location.**