

ERF file # 64 JK request

WELL SITE INSPECTION FORM



(C)

Well Name ? J. OLSON #1 API Number 05 - 087 - 5163  
Operator ? McRae - Casper (Ubrakto) Permit # \_\_\_\_\_  
Location NENW 26 - 1N - 55W County Morgan  
Field \_\_\_\_\_ Inspector ZPB

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) \_\_\_\_\_ Fail(N) X Date 9-20-91 ND \_\_\_\_\_ DG \_\_\_\_\_ WO \_\_\_\_\_ PR \_\_\_\_\_ SI \_\_\_\_\_ TA \_\_\_\_\_

=====

Date of Inspection Before/During Drilling \_\_\_\_\_

Surf. Csg. Size \_\_\_\_\_ Setting Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_ WOC time \_\_\_\_\_  
Consistent with APD casing Program? YES \_\_\_\_\_ NO \_\_\_\_\_ Returns \_\_\_\_\_  
Rig \_\_\_\_\_ BOP'S \_\_\_\_\_ Stage Tool Depth \_\_\_\_\_ Cmt. Vol. \_\_\_\_\_

Date of Inspection Before/During/After Completion \_\_\_\_\_

Prod. Csg. Set? \_\_\_\_\_ Completion Rig/Activity \_\_\_\_\_  
Drilling Pits: Closed \_\_\_\_\_ Open \_\_\_\_\_ Wellhead Installed: \_\_\_\_\_ Sign: Yes \_\_\_\_\_ No \_\_\_\_\_  
Tank ID: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Skim Tank/Pit: \_\_\_\_\_ Prod. Tanks: ( ) \_\_\_\_\_ BBLs  
Equipment \_\_\_\_\_ Meter Run: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bradenhead Press: \_\_\_\_\_ Fluid: No \_\_\_\_\_ Yes \_\_\_\_\_ Type \_\_\_\_\_ Well Cat. \_\_\_\_\_

AL/PA/DA Inspection

Date Plugged: \_\_\_\_\_ Date Permit Expired: \_\_\_\_\_  
Hole Plugged: Yes \_\_\_\_\_ No \_\_\_\_\_ Pits Backfilled: Yes \_\_\_\_\_ No \_\_\_\_\_  
Material Buried: Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ Site Clean: Yes \_\_\_\_\_ No \_\_\_\_\_  
Bond Release OK: Yes \_\_\_\_\_ No \_\_\_\_\_ Fed \_\_\_\_\_ Hole Marker: Yes \_\_\_\_\_ No \_\_\_\_\_

103/4" Date of Safety/Status Inspection \_\_\_\_\_  
Comments: 9 7/8" csg 4' above ground  
open with water level @ 100'  
4" Cores found near casing.

McRae no longer listed.

Violations: Yes ✓ No \_\_\_\_\_ Notice Sent: Yes \_\_\_\_\_ No \_\_\_\_\_ Date Sent: \_\_\_\_\_