

Inspection Photos

Location Name: AP 07-05 CA DATE 4-30-20

API#: 05-071-08652

INSP. #: 695102498



Colorado Oil & Gas Conservation Commission
37.09979, -104.93702, 2413.0m, 153°
2020/03/31 16:30:45



Colorado Oil & Gas Conservation Commission
37.09948, -104.93676, 2388.0m, 277°
2020/03/31 16:31:43

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos

Location Name: AP 07-05 CA DATE 4-30-20

API#: 05-071-08652

INSP. #: 695102498



PHOTO 3: UNMARKED UNUSED MARKER. COMPLY WITH NTO AND RULE 603.f. CA DATE 4-30-20

PHOTO 4: UNUSED EQUIPMENT. COMPLY WITH RULE 603.f.

Inspection Photos

Location Name: AP 07-05 CA DATE 4-30-20

API#: 05-071-08652

INSP. #: 695102498



PHOTO 5: STANDING OIL IN COMPRESSOR SKID.

Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-30-20.