

Final Reclamation Inspection

March 31, 2020

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 336400

Inspection Document #: 697501281

Weld County, CO

SWNE Section 18 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 1. Photo taken from a portion of the well location access road, facing North. Photo illustrates the Operator has performed final reclamation activities but vegetation has not met Rule 1004 standards.

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 2. Photo taken from the well location, facing West. Photo illustrates the Operator has failed to remove all equipment from location.

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 3. Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 4. Reference photo taken north of the well location, facing East. See comments under Photo 1. Photo illustrates bunch grasses.

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 5. Reference photo taken north of the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 6. Close up of reference photo #5. Photo illustrates *Artemisia* sp.

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 7. Photo taken from the offsite tank battery location, facing North. Photo illustrates Operator has removed all equipment from the associated offsite tank battery and has performed final reclamation activities with the evidence of drill rows and straw crimped mulch.

Inspection Photos
Location Name: KUGEL #32-18
Location ID: 336400



Photo 8. Photo taken from the offsite tank battery location, facing South. See comments under Photo 7.