

Inspection Photos

Loc#335432

Operator: Terra

Inspection #: 692402034

Inspection Date: 3/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed Loc#335432



Photo#2:
BMPs installed as a series.

Photo#3:
BMPs installed at West side of site.

March 24, 2020



Photo#4
Fence in disrepair.

March 24, 2020



Photo#5:
Sediment migration.

Inspection Photos: Terra Fed Loc#335432



Photo#6:
BMPs along East side of site.



Photo#7:
BMPs at South end of site

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fed Loc#335432



Photo#8:
BMPs at South end of site.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#9:
BMPs along West side of site

Inspection Photos: Terra Fed Loc#335432



Photo#10:
Sediment migration

March 24, 2020



Photo#11:
Sediment migration.



Photo#12:
BMPs at lower level of site.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#13:
BMPs at lower level of site

Inspection Photos: Terra Fed Loc#335432