

Inspection Photos

Location Name: Iles Dome Unit 64N92W 23SWNW

Location ID: 312756



Photo 1. Overview of location taken facing northeast.



Inspection Photos
Location Name: Iles Dome Unit 64N92W 23SWNW
Location ID: 312756



Photo 2. Stained soil under combustor.



Photo 3. Close-up of photo 2.