



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 9, 2020 1:13:28 PM MDT
Server Receive Date:	Apr 9, 2020 1:13:38 PM MDT
Reference Number:	20200409-18138860624
Location:	Gas Wells Rd, Ignacio, CO 81137, USA Apr 9, 2020 1:08:22 PM MDT [View Map]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 8, 2020
Select Run	Allison
Well Name	LUCHINI GAS UNIT 32-6-12 1
API Number	50070614300
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Fencing Clean Up Land Owner Debris Clean Up Contaminated Soils Grading of Well Pad

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed

Grading well pad



Completed work description of corrective action 2
 Photo of third corrective action completed

Cleaned up contaminated soil



Completed work description of corrective action 3
 Photo of fourth corrective action completed

Marked anchors



Completed work description
 Completed work description of corrective action 4
 Additional photos

Cleaned up contaminated soil and graded location.
 Fixed fence



Summary of all work completed

Picked up trash, Cleaned up contaminated soil on location and around well equipment and fixed fence around location.