

Inspection Photos

4/22/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 323997

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 323997



Photo 1: Photo taken from the west end of the Location, facing southwest. Photo of production equipment.

Photo 2: Continued from photo 1. Photo of sign on Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 323997



Photo 3: Continued from photo 1. Photo of the two 300 bbl AST. Tank on left “Condensate”, tank on right “produced water”.



Photo 4: Photo of well. Photo shows unused pipe stored on Locaiton.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 323997



Photo 5: Photo taken from the north end of the Location, facing north. Photo shows erosion degradation due to stormwater runoff from the Location. 6 foot measuring stick for reference.



Photo 6: Photo taken from the north end of the Location, facing north. Photo shows erosion degradation due to stormwater runoff from the Location. 6 foot measuring stick for reference.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 323997



Photo 7: Photo taken from the access road, north of the Location, facing south. Photo shows erosion degradation due to stormwater runoff from the Location. 6 foot measuring stick for reference.



Photo 8: Photo taken from the access road, north of the Location, facing north. Photo shows sediment deposition resulting from erosion degradation and stormwater runoff from the Location.