

Inspection Photos

Loc#334975

Operator: Caerus

Inspection Number: 692402129

Inspection Date: 4/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northeast and run over Anchor.

April 24 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Dever Loc#334975