

**Inspection Photos**  
**Location Name: Hillman 9-1**  
**Location ID: 417783**



**Photo 1 – Crude Oil tank with free standing fluid**



**Photo 2 – Crude Oil tank with free standing fluid**

**Inspection Photos**  
**Location Name: Hillman 9-1**  
**Location ID: 417783**



**Photo 3 – From the south the Tank Berm look S/SE**



**Photo 4 – Looking N/NW from where the fluid stopped.**



**Inspection Photos**  
**Location Name: Hillman 9-1**  
**Location ID: 417783**



**Photo 5 – Fluid settled S/SE from Tank**



**Photo 6 – Back of Tank and compromised containment**

**Inspection Photos**  
**Location Name: Hillman 9-1**  
**Location ID: 417783**



**Photo 7 – Crude Oil tank with free standing fluid**



**Photo 8 – Eastside of Tank**