

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2020

Submitted Date:

05/06/2020

Document Number:

689704658

FIELD INSPECTION FORM
 Loc ID 311597 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211502	WELL	PR	04/06/1998	GW	045-07262	EXXON GM 21-12	PR
259747	WELL	PR	04/09/2001	GW	045-07778	GM 321-12	PR
438288	WELL	PR	02/10/2015	OW	045-22462	GM 411-12	PR
438289	WELL	PR	02/10/2015	OW	045-22463	GM 531-12	PR
438290	WELL	PR	02/04/2015	GW	045-22464	GM 43-12	PR
438291	WELL	PR	02/10/2015	OW	045-22465	GM 342-12	PR
438292	WELL	PR	02/04/2015	GW	045-22466	GM 343-12	PR
438293	WELL	PR	02/09/2015	OW	045-22467	GM 332-12	PR
438294	WELL	PR	02/04/2015	GW	045-22468	GM 443-12	PR
438295	WELL	PR	02/04/2015	GW	045-22469	GM 542-12	PR
438296	WELL	PR	02/04/2015	GW	045-22470	GM 32-12	PR

General Comment:

Follow Up Field inspection

I, Inspector Mike Longworth, conducted a follow up field inspection.

Corrective actions have not been addressed from 02/25/2020 Inspection # 689704264

Tank capacities are faded on tank labels.

Tank capacities are too small to read at distance.

Install sign to comply with Rule 210.d.

C.A. Date 04/26/2020

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Unaddressed corrective action from 02/25/2020 Inspection # 689704264 Tank capacities are faded on tank labels. Tank capacities are too small to read at distance.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/26/2020

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211502	Type:	WELL	API Number:	045-07262	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	259747	Type:	WELL	API Number:	045-07778	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438288	Type:	WELL	API Number:	045-22462	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438289	Type:	WELL	API Number:	045-22463	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438290	Type:	WELL	API Number:	045-22464	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438291	Type:	WELL	API Number:	045-22465	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438292	Type:	WELL	API Number:	045-22466	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	438293	Type:	WELL	API Number:	045-22467	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 438294	Type: WELL	API Number: 045-22468	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 438295	Type: WELL	API Number: 045-22469	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 438296	Type: WELL	API Number: 045-22470	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402391614	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143553
689704659	Inspection 689704658 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5143551