

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2020

Submitted Date:

05/20/2020

Document Number:

679602681

FIELD INSPECTION FORM

Loc ID 427917	Inspector Name: Santistevan, Brittani	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 27 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: 10110 Name of Operator: GREAT WESTERN OPERATING COMPANY LLC Address: 1001 17TH STREET #2000 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427723	WELL	PR	01/13/2020	OW	123-35099	Raindance FC 23-369HN	PR
427727	WELL	PR	02/01/2019	OW	123-35100	Raindance FC 23-369HC	PR
432197	WELL	PR	02/10/2020	OW	123-37004	Raindance FC 26-032HC	PR
451091	WELL	PR	10/01/2019	OW	123-44982	Raindance FD 20-362HN	PR
451093	WELL	PR	07/21/2019	OW	123-44983	Raindance FD 20-282HN	PR
451094	WELL	PR	07/18/2019	OW	123-44984	Raindance FD 20-322HN	PR
451095	WELL	XX	06/14/2017		123-44985	Raindance FD 20-239HC	ND
451096	WELL	XX	06/14/2017		123-44986	Raindance FD 20-242HXX	ND
451097	WELL	PR	06/15/2019	OW	123-44987	Raindance FD 20-362HXX	PR
451098	WELL	PR	08/01/2019	OW	123-44988	Raindance FD 20-359HC	PR
451099	WELL	PR	07/16/2019	OW	123-44989	Raindance FD 20-319HN	PR
451101	WELL	PR	06/15/2019	OW	123-44990	Raindance FD 20-319HXX	PR
451102	WELL	PR	05/01/2019	OW	123-44991	Raindance FD 20-282HC	PR
451103	WELL	PR	06/15/2019	OW	123-44992	Raindance FD 20-242HN	PR
451168	WELL	PR	05/01/2019	LO	123-45007	Raindance FC 26-369HC	PR
451715	WELL	PR	05/01/2019	OW	123-45196	Raindance FD 20-399HC	PR
451877	WELL	XX	08/24/2017		123-45297	Raindance FC 26-192HC	ND
451878	WELL	XX	08/24/2017		123-45298	Raindance FC 26-209HN	ND
451879	WELL	XX	08/24/2017		123-45299	Raindance FC 26-232HXX	ND
451880	WELL	XX	08/24/2017		123-45300	Raindance FC 26-169HXX	ND

451881	WELL	XX	08/24/2017		123-45301	Raindance FD 20-239HN	ND
451882	WELL	XX	08/24/2017		123-45302	Raindance FC 26-232HN	ND

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 13		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	OTHER	STEEL AST		,
Comment:	Tanks appear to not be grounded. See attached photos.				
Corrective Action:	Comply with rule 605.c.				Date: 05/21/2020

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:			
Corrective Action:		Date:	
<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	427723	Type:	WELL	API Number:	123-35099	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	427727	Type:	WELL	API Number:	123-35100	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	432197	Type:	WELL	API Number:	123-37004	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451091	Type:	WELL	API Number:	123-44982	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451093	Type:	WELL	API Number:	123-44983	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451094	Type:	WELL	API Number:	123-44984	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	451095	Type:	WELL	API Number:	123-44985	Status:	XX	Insp. Status:	ND
Idle Well									
Purpose:	<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION				
Comment:	NOT DRILLED; FORM 2 DOC#: 400945965 EXPIRED JUNE 2019								
Corrective Action:						Date:			
Facility ID:	451096	Type:	WELL	API Number:	123-44986	Status:	XX	Insp. Status:	ND

Idle Well				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: SITE CONDITION				
Comment: NOT DRILLED; FORM 2 DOC#: 400945992 EXPIRED JUNE 2019				
Corrective Action:				Date:
Facility ID:	451097	Type:	WELL	API Number: 123-44987 Status: PR Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID:	451098	Type:	WELL	API Number: 123-44988 Status: PR Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID:	451099	Type:	WELL	API Number: 123-44989 Status: PR Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID:	451101	Type:	WELL	API Number: 123-44990 Status: PR Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID:	451102	Type:	WELL	API Number: 123-44991 Status: PR Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID:	451103	Type:	WELL	API Number: 123-44992 Status: PR Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID:	451168	Type:	WELL	API Number: 123-45007 Status: PR Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:				Date:
Facility ID:	451715	Type:	WELL	API Number: 123-45196 Status: PR Insp. Status: PR

Producing Well				
Comment:	PR			
Corrective Action:		Date:		
Facility ID:	451877	Type:	WELL	API Number: 123-45297 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment:	NOT DRILLED; FORM 2 DOC#: 402080766 (IN PPROCESS)			
Corrective Action:		Date:		
Facility ID:	451878	Type:	WELL	API Number: 123-45298 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment:	NOT DRILLED; FORM 2 DOC#: 402080767 (IN PROCESS)			
Corrective Action:		Date:		
Facility ID:	451879	Type:	WELL	API Number: 123-45299 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment:	NOT DRILLED; FORM 2 DOC#: 402080770 (IN PROCESS)			
Corrective Action:		Date:		
Facility ID:	451880	Type:	WELL	API Number: 123-45300 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment:	NOT DRILLED; FORM 2 DOC#: 402080765 (IN PROCESS)			
Corrective Action:		Date:		
Facility ID:	451881	Type:	WELL	API Number: 123-45301 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment:	NOT DRILLED; FORM 2 DOC# 400945974 EXPIRED AUG. 2019			
Corrective Action:		Date:		
Facility ID:	451882	Type:	WELL	API Number: 123-45302 Status: XX Insp. Status: ND
Idle Well				
Purpose:	<input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: SITE CONDITION	
Comment:	NOT DRILLED; FORM 2 DOC#: 402080769 (IN PROCESS)			
Corrective Action:		Date:		

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>**Weather Conditions: sunny, dry ground, windy</p> <p>On Wednesday, May 20, 2020 at approximately 11:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at RAINDANCE FD 10-219HN (GREAT WESTERN OIL & GAS), at location #: 427917 in WELD COUNTY Colorado.</p> <p>While there, I observed producing wellheads.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Two tanks connected to wellheads does not appear to be grounded. GROUND TANKS IN ACCORDANCE TO RULE 605.C. (Corrective Action Date: May 21, 2020) See attached photo #30.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	05/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402403322	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155747
679602682	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155734