

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2020

Submitted Date:

05/20/2020

Document Number:

689704728**FIELD INSPECTION FORM**

Loc ID 447695	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>950 17TH STREET, SUITE 1900</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447698	WELL	PR	01/09/2018	GW	045-23310	BMC B 12D-18-07-95	PR
447706	WELL	PR	03/24/2018	GW	045-23318	BMC B 23D-18-07-95	PR
447707	WELL	PR	03/27/2018	GW	045-23319	BMC B 14A-18-07-95	PR
447708	WELL	PR	02/02/2018	GW	045-23320	BMC B 23B-18-07-95	PR
447709	WELL	PR	03/28/2018	GW	045-23321	BMC B 23A-18-07-95	PR
447710	WELL	PR	03/01/2018	GW	045-23322	BMC B 13B-18-07-95	PR
447711	WELL	PR	02/08/2018	GW	045-23323	BMC B 13C-18-07-95	PR
447712	WELL	PR	02/22/2018	GW	045-23324	BMC B 23C-18-07-95	PR
447713	WELL	PR	02/23/2018	GW	045-23325	BMC B 13D-18-07-95	PR
447715	WELL	PR	01/19/2018	GW	045-23327	BMC B 13A-18-07-95	PR
447716	WELL	PR	01/14/2018	GW	045-23328	BMC B 22D-18-07-95	PR
449469	WELL	PR	12/10/2017	GW	045-23477	BMC B 32B-13-07-96	PR
449470	WELL	PR	11/29/2017	GW	045-23478	BMC B 42A-13-07-96	PR
449474	WELL	PR	11/23/2017	GW	045-23479	BMC B 41C-13-07-96	PR
449475	WELL	PR	12/30/2017	GW	045-23480	BMC B 42C-13-07-96	PR
449478	WELL	PR	02/10/2018	GW	045-23481	BMC B 43B-13-07-96	PR
449479	WELL	PR	11/27/2017	GW	045-23482	BMC B 32A-13-07-96	PR
449480	WELL	PR	04/04/2018	GW	045-23483	BMC B 43A-13-07-96	PR
449482	WELL	PR	01/07/2018	GW	045-23484	BMC B 42D-13-07-96	PR
449484	WELL	PR	12/21/2017	GW	045-23485	BMC B 32C-13-07-96	PR

449485	WELL	PR	02/28/2018	GW	045-23486	BMC B 43C-13-07-96	PR
449487	WELL	PR	12/22/2017	GW	045-23487	BMC B 42B-13-07-96	PR
449489	WELL	PR	11/28/2017	GW	045-23488	BMC B 41B-13-07-96	PR
449490	WELL	PR	11/28/2017	GW	045-23489	BMC B 41D-13-07-96	PR

General Comment:

I, Inspector Mike Longworth, conducted an inspection on site in response of Complaintants 18200448946, 18200448939, 18200448940
During this inspection the following possible compliance issues were observed:

Chemical pumps on chemical containers at wells has loose fittings dripping fluid. The top of the secondary container is stained with chemical.

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

C.A. Date 05/20/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities									
Facility ID:	<u>447698</u>	Type:	<u>WELL</u>	API Number:	<u>045-23310</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Complaint									
Comment:	I, Inspector Mike Longworth, conducted an inspection on site in response of Complainants 18200448946, 18200448939, 18200448940 Chemical pumps on chemical containers at wells has loose fittings dripping fluid. The top of the secondary conatiner is stained with chemical. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. C.A Date 05/20/2020								
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.						Date:	<u>05/21/2020</u>	
Facility ID:	<u>447706</u>	Type:	<u>WELL</u>	API Number:	<u>045-23318</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447707</u>	Type:	<u>WELL</u>	API Number:	<u>045-23319</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447708</u>	Type:	<u>WELL</u>	API Number:	<u>045-23320</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447709</u>	Type:	<u>WELL</u>	API Number:	<u>045-23321</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447710</u>	Type:	<u>WELL</u>	API Number:	<u>045-23322</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447711</u>	Type:	<u>WELL</u>	API Number:	<u>045-23323</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447712</u>	Type:	<u>WELL</u>	API Number:	<u>045-23324</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447713</u>	Type:	<u>WELL</u>	API Number:	<u>045-23325</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447715</u>	Type:	<u>WELL</u>	API Number:	<u>045-23327</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>447716</u>	Type:	<u>WELL</u>	API Number:	<u>045-23328</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>449469</u>	Type:	<u>WELL</u>	API Number:	<u>045-23477</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>449470</u>	Type:	<u>WELL</u>	API Number:	<u>045-23478</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>449474</u>	Type:	<u>WELL</u>	API Number:	<u>045-23479</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>449475</u>	Type:	<u>WELL</u>	API Number:	<u>045-23480</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>449478</u>	Type:	<u>WELL</u>	API Number:	<u>045-23481</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Facility ID: 449479	Type: WELL	API Number: 045-23482	Status: PR	Insp. Status: PR
Facility ID: 449480	Type: WELL	API Number: 045-23483	Status: PR	Insp. Status: PR
Facility ID: 449482	Type: WELL	API Number: 045-23484	Status: PR	Insp. Status: PR
Facility ID: 449484	Type: WELL	API Number: 045-23485	Status: PR	Insp. Status: PR
Facility ID: 449485	Type: WELL	API Number: 045-23486	Status: PR	Insp. Status: PR
Facility ID: 449487	Type: WELL	API Number: 045-23487	Status: PR	Insp. Status: PR
Facility ID: 449489	Type: WELL	API Number: 045-23488	Status: PR	Insp. Status: PR
Facility ID: 449490	Type: WELL	API Number: 045-23489	Status: PR	Insp. Status: PR

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402402783	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155075
689704729	Inspection 689704728 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155073