

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2020

Submitted Date:

05/20/2020

Document Number:

700600112**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections
Beardslee, Tom		tom.beardslee@state.co.us	
Harkins, Liz		lharkins@fremontpetroleum.com	

General Comment:[This is an environmental inspection to document status of Spill #476499.](#)[Operator reported spill via phone call to area Environmental Protection Specialist.](#)[Inspection found spill was entirely contained within secondary containment earthen berm. See attached photos.](#)[New tank on location and will replace tank that was source of spill. Operator informed of requirement to adhere to new tank battery setback rules if tank battery is to be reconstructed in another location. Operator has filed Form 19 #402401754 to report spill of greater than 5 bbl oil inside containment. Operator shall adhere to Conditions of Approval on approved Form 19.](#)

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 15

Comment: Submit Form 19 as required per Rule 906.

Corrective Action: Operator has already submitted required Form 19. No response needed for this corrective action.

Date: 05/19/2020

Reportable: YES

GPS: Lat 38.273248

Long -105.115624

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location: Comment:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402403268	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155676
700600113	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155670
700600114	Environmental Inspection Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155671