

# Inspection Photos

6/12/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 445862

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC # 10456**  
**Location ID: 445862**



**Photo 1:** Photo taken from the North end of the Location facing southeast. Photos 1-3 provide an overview of the Location from southeast, south to southwest. Photo shows interim reclamation of the Location is in process.



**Photo 2:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 445862



**Photo 3:** See comments under photo 1.



**Photo 4:** Photo taken from the southwest end of the Pad. Photo shows Operator has used a hydromulch to stabilize the seeded soils of the Location. Photo shows areas of the cut slope where soils show sign of destabilization.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 445862



**Photo 5:** Photo of what appears to be the capped 045-23206 well. There does not appear to be signage for this well.



**Photo 6:** Photo of what appears to be 3 conductor settings for wells on the Location. There does not appear to be signage associated with these conductor settings/wells.