

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/06/2020

Submitted Date:

08/07/2020

Document Number:

696103470**FIELD INSPECTION FORM**Loc ID 302537 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------------|---------------------------------|
| , | | dnr_cogccengineering@state.co.us | |
| , | | NBL_DJBU_Inspections@nblenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 299234 | WELL | PR | 12/01/2019 | OW | 123-29299 | GULLEY 17-25 | SI |

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 4 Location IDs (305486, 302537, 302596, 330136).
(Well(s): 4: Shut-In | SI).

Refer to Field Inspection Report doc. #696103468 and/or Location ID #305486
for Battery / Facility, Equipment info.

| Location | | | | |
|--|---|--------|--|-----------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Adequate | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | | | | |
| Comment: | Refer to Field Inspection Report doc. #696103468 and/or Location ID #305486 for Battery / Facility, Equipment info. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | | | | |
| Comment: | Refer to Field Inspection Report doc. #696103468 and/or Location ID #305486 for Battery / Facility, Equipment info. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Iron panel. | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Bradenhead | # 1 | | | corrective date |
| Comment: | Appears plumbed to surface. | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: | # | | | |
| Comment: | Refer to Field Inspection Report doc. #696103468 and/or Location ID #305486 for Battery / Facility, Equipment info. | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Tanks and Berms:

| | | | | | | |
|--------------------|--|----------|---------------------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| | | | CENTRALIZED BATTERY | | 40.486991,-104.581638 | |
| Comment: | Centralized Battery serves 4 Location IDs (305486, 302537, 302596, 330136). Refer to Field Inspection Report doc. #696103468 and/or Location ID #305486 for Battery / Facility, Equipment info. | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | | | | |
|------------------|--|--|--|--|--|
| Condition | | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|---|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 299234 | Type: | WELL | API Number: | 123-29299 | Status: | PR | Insp. Status: | SI |
| Idle Well | | | | | | | | | |
| Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: EQUIPMENT ONSITE | | | | | | | | | |
| Comment: Shut-In SI. Observed production valves shut. Locked-Out, Tagged-Out LOTO. Dated: 06/09/2020. | | | | | | | | | |
| Corrective Action: | | | | | | | | | |
| Date: | | | | | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On THU 08/06/2020 at approximately 15:47 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: GULLEY /17-25 Location ID: 302537 Well Name: Gulley 17-25 API: 05-123-29299 Location County: Weld County, Colorado Weather: Partly cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 4 Location IDs (305486, 302537, 302596, 330136). (Well(s): 4: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696103468 and/or Location ID #305486 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 08/07/2020 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696103471 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5219457 |