

Inspection Photos  
Location Name: Calvary Farms 19-D Pad  
Location ID: 457898




Photo 1: Tank Battery Sign



Photo 2: Tank Battery

# Inspection Photos Location Name: Calvary Farms 19-D Pad Location ID: 457898




Photo 3: No BBLS on H2O tank




Photo 4: NO BBLS on H2O tank



**Inspection Photos**  
**Location Name: Calvary Farms 19-D Pad**  
**Location ID: 457898**



**Photo 5: No labeling on tank**



**Photo 6: No labeling on tank**



**Inspection Photos**  
**Location Name: Calvary Farms 19-D Pad**  
**Location ID: 457898**



**Photo 7: No labeling on tank**



**Photo 8: Unused equipment**





**Inspection Photos**  
**Location Name: Calvary Farms 19-D Pad**  
**Location ID: 457898**



**Photo 9: Wellhead Sign**



**Photo 10: Stained soil**





**Inspection Photos**  
**Location Name: Calvary Farms 19-D Pad**  
**Location ID: 457898**



**Photo 11: Wellhead Sign**



**Photo 12: Stained soil**

**Inspection Photos**  
**Location Name: Calvary Farms 19-D Pad**  
**Location ID: 457898**



**Photo 13: Stained soil**