

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/11/2020

Submitted Date:

08/11/2020

Document Number:

679603193

FIELD INSPECTION FORM

Loc ID 457898	Inspector Name: Santistevan, Brittani	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10261 Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC Address: 730 17TH ST STE 500 City: DENVER State: CO Zip: 80202				Findings: 24 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
,		wellinspections@bayswater.us	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457893	WELL	XX	10/15/2018		123-48143	Calvary Farms E-20-21HC	ND
457894	WELL	XX	10/15/2018		123-48144	Calvary Farms K-20-21HC	ND
457895	WELL	PR	09/01/2019		123-48145	Calvary Farms A-20-21HN	PR
457896	WELL	XX	10/15/2018		123-48146	Calvary Farms G-20-21HN	ND
457897	WELL	PR	09/01/2019		123-48147	Calvary Farms B-20-21HC	PR
457899	WELL	XX	10/15/2018		123-48148	Calvary Farms F-20-21HN	ND
457900	WELL	PR	09/01/2019		123-48149	Calvary Farms C-20-21HN	PR
457901	WELL	PR	09/01/2019		123-48150	Calvary Farms BA-20-21HN	PR
457902	WELL	XX	10/15/2018		123-48151	Calvary Farms EA-20-21HN	ND
457903	WELL	XX	10/15/2018		123-48152	Calvary Farms H-20-21HC	ND
457904	WELL	XX	10/15/2018		123-48153	Calvary Farms D-20-21HN	ND
457905	WELL	XX	10/15/2018		123-48154	Calvary Farms HA-20-21HN	ND
457906	WELL	XX	10/15/2018		123-48155	Calvary Farms J-20-21HN	ND
457907	WELL	XX	10/15/2018		123-48156	Calvary Farms KA-20-21HN	ND
457908	WELL	XX	10/15/2018		123-48157	Calvary Farms I-20-21HN	ND
457909	WELL	XX	10/15/2018		123-48158	Calvary Farms L-20-21HN	ND

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No BBLS on two tanks, no labeling on two tanks. See attached photos.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	09/11/2020
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location. See attacehd photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	09/11/2020
Type	OTHER		
Comment:	Stained soil on location. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).d.	Date:	09/11/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	3	OTHER	BV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	6	500 BBLS	STEEL AST		40.564700,-104.698400	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities					
Facility ID: 457893	Type: WELL	API Number: 123-48143	Status: XX	Insp. Status: ND	
Idle Well					
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: SITE CONDITION					
Comment: NOT DRILLED Form 2 DOC#: 401680979 in well file. Expires OCT 2020					
Corrective Action:					Date:
Facility ID: 457894	Type: WELL	API Number: 123-48144	Status: XX	Insp. Status: ND	
Idle Well					
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: SITE CONDITION					
Comment: NOT DRILLED Form 2 DOC#: 401681609 in well file. Expires OCT 2020					
Corrective Action:					Date:
Facility ID: 457895	Type: WELL	API Number: 123-48145	Status: PR	Insp. Status: PR	
Producing Well					
Comment: PR					
Corrective Action:					Date:
Facility ID: 457896	Type: WELL	API Number: 123-48146	Status: XX	Insp. Status: ND	
Idle Well					
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: SITE CONDITION					
Comment: NOT DRILLED Form 2 DOC#: 401681083 in well file. Expires OCT 2020					
Corrective Action:					Date:
Facility ID: 457897	Type: WELL	API Number: 123-48147	Status: PR	Insp. Status: PR	
Producing Well					
Comment: PR					
Corrective Action:					Date:
Facility ID: 457899	Type: WELL	API Number: 123-48148	Status: XX	Insp. Status: ND	
Idle Well					
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: SITE CONDITION					
Comment: NOT DRILLED Form 2 DOC# 401681047 in well file. Expires OCT 2020					
Corrective Action:					Date:
Facility ID: 457900	Type: WELL	API Number: 123-48149	Status: PR	Insp. Status: PR	
Producing Well					
Comment: PR					

Corrective Action:		Date:	
Facility ID: 457901	Type: WELL	API Number: 123-48150	Status: PR Insp. Status: PR
Producing Well			
Comment: PR			
Corrective Action:		Date:	
Facility ID: 457902	Type: WELL	API Number: 123-48151	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION		
Comment: NOT DRILLED Form 2 DOC# 401681037 in well file. Expires OCT 2020			
Corrective Action:		Date:	
Facility ID: 457903	Type: WELL	API Number: 123-48152	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION		
Comment: NOT DRILLED Form 2 DOC#: 401679372 in well file. Expires OCT 2020			
Corrective Action:		Date:	
Facility ID: 457904	Type: WELL	API Number: 123-48153	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION		
Comment: NOT DRILLED Form 2 DOC#: 401680916 in well file. Expires OCT 2020			
Corrective Action:		Date:	
Facility ID: 457905	Type: WELL	API Number: 123-48154	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION		
Comment: NOT DRILLED Form 2 DOC#: 401681107 in well file. Expires OCT 2020			
Corrective Action:		Date:	
Facility ID: 457906	Type: WELL	API Number: 123-48155	Status: XX Insp. Status: ND
Idle Well			
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned	Reminder: SITE CONDITION		
Comment: NOT DRILLED Form 2 DOC#: 401681241 in well file. Expires OCT 2020			
Corrective Action:		Date:	
Facility ID: 457907	Type: WELL	API Number: 123-48156	Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED
Form 2 DOC#: 401681672 in well file. Expires OCT 2020

Corrective Action:

Date:

Facility ID: 457908 Type: WELL API Number: 123-48157 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED
Form 2 DOC#: 401681139 in well file. Expires OCT 2020

Corrective Action:

Date:

Facility ID: 457909 Type: WELL API Number: 123-48158 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED
Form 2 DOC#: 401681704 in well file. Expires OCT 2020

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>**Weather Conditions: sunny, dry ground</p> <p>On Tuesday, August 11, 2020 at approximately 13:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at CALVARY FARM 19-D PAD (Bayswater Exploration & Production LLC), at location #: 457898 in WELD COUNTY Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. No BBLs on two H2O tanks and no labeling/signage on 3 tanks. Install sign to comply with Rule 210.d. (Corrective Action Date: September 11, 2020) See attached photos #3-7. 2. Unused equipment on location. Remove to comply with Rule 603.f. (Corrective Action Date: September 11, 2020) See attached photo #8. 3. Appears to be stained soil on location at two wellheads. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f. (2).d. (Corrective Action Date: September 11, 2020) See attached photos #10, 12, 13. <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	08/11/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603194	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5221863