

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402472182

Date Received:

08/20/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 6 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

NBL_DJBU_Inspections@nblenergy.com

Trena.Hallback@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690900114

Inspection Date: 08/05/2020

FIR Submit Date: 08/07/2020

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: NWN Sec: 18 Twp: 4N Range: 64W Meridian: 6
W

Latitude: 40.317838 Longitude: -104.596681

FACILITY - API Number: 05-123- -00 Facility ID: 287848

Facility Name: CENTRALIZED LAND TREATMEN FACILITY Number: _____

Qtrqtr: NWN Sec: 18 Twp: 4N Range: 64W Meridian: 6
W

Latitude: 40.317838 Longitude: -104.596681

CORRECTIVE ACTIIONS:

1 CA# 141076

Corrective Action: Comply with Rule 908.b.(5)C

Date: 08/20/2020

Response: CA COMPLETED

Date of Completion: 08/19/2020

Operator Comment:

Noble Energy has repaired the fence and said fence is currently kept locked.

COGCC Decision: Approved

COGCC Representative: See Inspection Doc #690900116 and attached photos.

2 CA# 141077

Corrective Action: Install/remove signs to comply with Rule 210.c. Date: 09/29/2020

Response: CA COMPLETED Date of Completion: 08/19/2020

Operator Comment: Noble Energy has removed the old signage and replaced it with updated company information.

COGCC Decision: Approved

COGCC Representative: See Inspection Doc #690900116 and attached photos.

3 CA# 141078

Corrective Action: Comply with Rule 603.f . Date: 08/21/2020

Response: CA COMPLETED Date of Completion: 08/19/2020

Operator Comment: Noble Energy has removed the 1" PVC line on southwest corner of yard. The trash/debris that was located inside and immediately outside of fencing has been removed.

COGCC Decision: Approved

COGCC Representative: See Inspection Doc #690900116 and attached photos.

5 CA# 141080

Corrective Action: Comply with Rule 907.e. Date: 08/22/2020

Response: CA COMPLETED Date of Completion: 08/14/2020

Operator Comment: Impacted materials removed and taken to Waste Management for disposal.

COGCC Decision: Approved

COGCC Representative: See Inspection Doc #690900116 and attached photos.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Doughery Signed: _____

Title: EHS Specialist Date: 8/20/2020 1:24:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402472182	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files