

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/18/2020

Submitted Date:

08/18/2020

Document Number:

695103170

FIELD INSPECTION FORM

Loc ID 309423 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10351
Name of Operator: WAPITI OPERATING LLC
Address: 1310 W SAM HOUSTON PKWY N
City: HOUSTON State: TX Zip: 77043

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	Production superintendent
Berry, Matthew	575-445-6785/505-652-8275	mberry@wapitienergy.com	Production Foreman
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	EHS Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294889	WELL	PR	08/12/2008	GW	071-09516	VPR C 203	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bradenhead

1

Comment: IS PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: NO GAS METER CALIBRATION REPORT ON LOCATION.

Corrective Action: PROVIDE AREA FIELD INSPECTOR (@ tombeardslee@state.co.us) A COPY OF THE GAS METER CALIBRATION RECORD OR KEEP A COPY OF LAST CALIBRATION RECORD ON LOCATION.

Date: 09/18/2020

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 294889 Type: WELL API Number: 071-09516 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402470373	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227261
695103171	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227252