

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/18/2020

Submitted Date:

08/18/2020

Document Number:

695103176

**FIELD INSPECTION FORM**Loc ID 307701 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	EHS Specialist
Burger, Craig		craig.burger@state.co.us	
Duran, Alicia		alicia.duran@state.co.us	
Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	Production superintendent
Berry, Matthew	575-445-6785/505-652-8275	mberry@wapitienergy.com	Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89239	WELL	PR	09/15/1999	GW	071-06819	VPR C 7	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment:

PHOTO 3: BRADENHEAD IS NOT PLUMBED TO SURFACE.

Corrective Action:

PLUMB BRADENHEAD TO SURFACE, COMPLY WITH RULE 608e.

Date: 11/18/2020

Type: Gas Meter Run

# 1

Comment:

NO GAS METER LOG ON LOCATION.

Corrective Action:

PROVIDE AREA FIELD INSPECTOR (@ tombeardslee@state.co.us) A COPY OF THE GAS METER CALIBRATION RECORD OR KEEP A COPY OF LAST CALIBRATION RECORD ON LOCATION.

Date: 09/18/2020**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 89239 Type: WELL API Number: 071-06819 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402470376	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227264">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227264</a>
695103177	INSPECTION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227255">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5227255</a>