

BP L48 San Juan



V2 Compliance Follow Up Form

18152298646

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200820-18152298646

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 20, 2020 12:52:52 PM MDT

Indian Rte 114, Durango, CO 81303, USA

Aug 20, 2020 12:50:24 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 18, 2020
Well Name	ELDRIDGE 25-01 2
API Number	50670956600
Select State	Colorado
Work type	BLM Inspection AR
Action Complete	Compliance Inspection Actions Clean up Operator Debris Clean Up Weed Debris Clean Up Contaminated Soils Replaced/Repaired Tank Signs
Photo of first corrective action completed	



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Cleaned up weeds

Photo of third corrective action completed



Completed work description of corrective action 3

Cleaned up contaminated soil

Photo of fourth corrective action completed



Completed work description

Picked up trash

Completed work description of corrective action 4

Installed new tank sign

Additional photos

**Summary of all work completed**

Compliance, cleaned up contaminated soil ,
picked up weeds , installed tank sign and picked
up trash