

BP L48 San Juan



V2 Compliance Follow Up Form

18152326949

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200820-18152326949

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 20, 2020 1:11:17 PM MDT

Indian Rte 114, Durango, CO 81303, USA

Aug 20, 2020 1:09:03 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 19, 2020
Well Name	ELDRIDGE 25-02 1
API Number	50670743200
Select State	Colorado
Work type	BLM Inspection AR
Action Complete	Clean up Operator Debris Clean Up Weed Debris Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up contaminated soil

Photo of third corrective action completed



**Completed work description of corrective
action 3**

Cleaned up weeds

Photo of fourth corrective action completed



Completed work description

Picked up trash

Completed work description of corrective action 4

Picked up trash

Summary of all work completed

Compliance , cleaned up contaminated soil ,
picked up trash and picked up weeds