

BP L48 San Juan



V2 Compliance Follow Up Form

18153221449

Reference Number: 20200828-18153221449
Form Name: V2 Compliance Follow Up Form
Submitter Name: Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com
Submission Date: Aug 21, 2020 12:57:26 PM MDT
Location: 1837 Anna Rd, Ignacio, CO 81137, USA
Aug 21, 2020 12:55:58 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name kenneth.canterbury@crossfire-llc.com
Well Name WARD, JW GAS UNIT A 1
API Number 50670732900
Select State Colorado
Work type COGCC Inspection AR
Action Complete Compliance Inspection Actions
Clean up Operator Debris
Clean Up Land Owner Debris
Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective Action 1 Compliance
Photo of second corrective action completed



Completed work description of corrective action 2

Picked up weeds

Photo of third corrective action completed



Completed work description of corrective action 3

Cleaned up stains

Photo of fourth corrective action completed



Completed work description

Picked up weeds

Completed work description of corrective action 4

Picked up trash

Summary of all work completed

Compliance , picked up weeds and picked up trash