

BP L48 San Juan



V2 Compliance Follow Up Form

18153221447

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200828-18153221447

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Aug 21, 2020 1:46:14 PM MDT

1923 Co Rd 309A, Ignacio, CO 81137, USA

Aug 21, 2020 1:44:48 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 20, 2020
Well Name	REA, EARL GAS UNIT 1
API Number	50670698900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other Clean up Operator Debris Clean Up Land Owner Debris Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



**Completed work description of corrective
action 2**

Picked up trash

Photo of third corrective action completed



Completed work description of corrective action 3

Cleaned up stains

Photo of fourth corrective action completed



Completed work description

Installed new well equipment sign

Completed work description of corrective action 4

Installed new well equipment sign

Additional photos



Summary of all work completed

Compliance , cleaned up stains, picked up trash and installed new equipment signs