

Inspection Photos
Location Name: Grizzly 3-32H
Location ID: 436007



Photo 1. Overview of location taken facing northeast.



Inspection Photos
Location Name: Grizzly 3-32H
Location ID: 436007



Photo 2. Equipment stored at wellhead.



Photo 3. Tank labels becoming faded.

