

Inspection Photos

API: 071-06406

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 9/11/2020

Inspection Photos



Photo 1. Facing west toward the reclaimed access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 9/11/2020

Inspection Photos



Photo 2. Facing west toward the location. Vegetation is progressing at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 9/11/2020

Inspection Photos



Photo 3. Facing northeast at the location. Vegetation is progressing at the however, there are areas that are sparse that could use additional hand seeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 9/11/2020