

Inspection Photos
Location Name: Rasmussen #2
Location ID: 336405



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Rasmussen #2
Location ID: 336405



Photo 3 Weeds overgrown around wellsite

Photo 4 Weeds overgrown around wellsite