

Inspection Photos
Location Name: Leffler 8-21 Pad
Location ID: 450030



Photo 1: Tank Battery Sign



Photo 2: Tank Battery

Inspection Photos
Location Name: Leffler 8-21 Pad
Location ID: 450030



Photo 3: Wellhead Sign



Photo 4: Stained soil

