

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #2050 from entrance to location.



Photo #2051 from entrance to location.

## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



**Photo #1592 from inspection #699801440 conducted on 7/14/20.**



**Photo #2052 Unused equipment.**



## Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



**Photo #2053 Vegetation growing on secondary containment.**