

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /21-41

Location ID: 312742

Network: Oct 19, 2020 at 11:03:58 AM MD
Local: Oct 19, 2020 at 11:03:59 AM MD



Photo #2040 from entrance to location.

Network: Oct 19, 2020 at 11:04:01 AM MD
Local: Oct 19, 2020 at 11:04:02 AM MD



Photo #2041 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Homer Deep Unit /21-41

Location ID: 312742



Photo #2042 Channel erosion accruing on east side of location.



Photo #2043 Channel erosion accruing on east side of location.