

# Final Reclamation Inspection

October 30, 2020

Operator: WESTERN OPERATING COMPANY - 95620

API #: 05-123-14822

Inspection Document #: 697502143

Weld County, CO

NWSW Section 14 T6N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Photo taken from the associated offsite tank battery, facing East. Photo illustrates the Operator has failed to remove all equipment. This failure to remove equipment also appears to be inhibiting the surface owner from putting an area into crop production. Winter wheat is currently planted in the adjacent reference areas.



**Photo 2.** Photo taken from the well location, facing East. Photo illustrates some winter wheat germination but COGCC staff will have to make a future assessment to ensure compliance with Rule 1004 vegetative standards.

Note: there did appear to be a lack of germination within the well location versus reference areas.

Inspection Photos  
Location Name: FOSTER #14-2  
API #: 05-123-14822



**Photo 3.** Photo taken from the well location, facing South. See comments under Photo 2.

Inspection Photos  
Location Name: FOSTER #14-2  
API #: 05-123-14822



**Photo 4.** Photo taken from the well location, facing West. See comments under Photo 2.

Inspection Photos  
Location Name: FOSTER #14-2  
API #: 05-123-14822



**Photo 5.** Photo taken from the well location, facing North. See comments under Photo 2.