

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/28/2020

Submitted Date:

10/28/2020

Document Number:

679603435**FIELD INSPECTION FORM**Loc ID 455319 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10177Name of Operator: ENERPLUS RESOURCES (USA) CORPORATIONAddress: 950 17TH STREET #2200City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone        | Email                | Comment                               |
|--------------|--------------|----------------------|---------------------------------------|
| ,            | 720-279-5512 | smiller@enerplus.com | <a href="#">All RI/CI inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name            | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 455318      | WELL | XX     | 06/11/2020  |            | 123-46985 | Lethbridge 8-67-20-19C   | ND          |
| 455320      | WELL | PR     | 09/01/2019  | OW         | 123-46986 | Edmonton 8-67-20-19N     | PR          |
| 455321      | WELL | XX     | 06/11/2020  |            | 123-46987 | Airdrie 8-67-20-19C      | ND          |
| 455322      | WELL | XX     | 06/11/2020  |            | 123-46988 | Medicine Hat 8-67-20-19C | ND          |
| 455323      | WELL | XX     | 06/11/2020  |            | 123-46989 | Red Deer 8-67-21-22C     | ND          |
| 455324      | WELL | PR     | 09/01/2019  |            | 123-46990 | St. Albert 8-67-21-22C   | PR          |
| 455325      | WELL | XX     | 06/11/2020  |            | 123-46991 | Calgary 8-67-21-22C      | ND          |
| 455326      | WELL | XX     | 06/11/2020  |            | 123-46992 | GRAND PRARIE 8-67-21-22N | ND          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | WELLHEAD  |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | BATTERY   |       |            |
| Comment:             | Adequate  |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | TANK LABELS/PLACARDS                                    |       |            |
| Comment:             | Two tanks do not contain labeling. See attached photos. |       |            |
| Corrective Action:   | Instal sign to comply with Rule 210.d.                  | Date: | 12/28/2020 |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Adequate |       |  |
| Corrective Action: |          | Date: |  |

|                       |     |       |                 |
|-----------------------|-----|-------|-----------------|
| <b>Equipment:</b>     |     |       | corrective date |
| Type: Bird Protectors | # 4 |       |                 |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Flare           | # 1 |       |                 |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Compressor      | # 2 |       |                 |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Plunger Lift    | # 2 |       |                 |
| Comment:              |     |       |                 |
| Corrective Action:    |     | Date: |                 |
| Type: Gas Meter Run   | # 2 |       |                 |

|                                   |     |       |  |
|-----------------------------------|-----|-------|--|
| Comment:                          |     | Date: |  |
| Corrective Action:                |     | Date: |  |
| Type: Bradenhead                  | # 2 |       |  |
| Comment:                          |     | Date: |  |
| Corrective Action:                |     | Date: |  |
| Type: Emission Control Device     | # 2 |       |  |
| Comment:                          |     | Date: |  |
| Corrective Action:                |     | Date: |  |
| Type: Horizontal Heated Separator | # 2 |       |  |
| Comment:                          |     | Date: |  |
| Corrective Action:                |     | Date: |  |

**Tanks and Berms:**

| Contents           | #     | Capacity | Type           | Tank ID | SE GPS |
|--------------------|-------|----------|----------------|---------|--------|
| OTHER              | 2     | OTHER    | FIBERGLASS AST |         | ,      |
| Comment:           |       |          |                |         |        |
| Corrective Action: | Date: |          |                |         |        |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  | UNKNOWN  |
| Other (Capacity) | UNKNOWN  |
| Other (Type)     |          |

**Berms**

| Type               | Capacity                                 | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--|---------------------|---------------------|-------------|
|                    |  |                     |                     |             |
| Comment:           | Shares containment with crude oil tanks. |                     |                     |             |
| Corrective Action: | Date:                                    |                     |                     |             |

| Contents           | #     | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|-------|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 6     | 400 BBLs | STEEL AST |         | 40.642800,-104.908500 |
| Comment:           |       |          |           |         |                       |
| Corrective Action: | Date: |          |           |         |                       |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: | Date:    |                     |                     |             |



| Inspected Facilities  |            |                       |            |                  |       |
|---|------------|-----------------------|------------|------------------|-------|
| Facility ID: 455318   | Type: WELL | API Number: 123-46985 | Status: XX | Insp. Status: ND |       |
| <b>Idle Well</b>  |            |                       |            |                  |       |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: SITE CONDITION |            |                       |            |                  |       |
| Comment: NOT DRILLED<br>Form 2 DOC#: 402341125 expires JUNE 2022  |            |                       |            |                  |       |
| Corrective Action:  |            |                       |            |                  | Date: |
| Facility ID: 455320   | Type: WELL | API Number: 123-46986 | Status: PR | Insp. Status: PR |       |
| <b>Producing Well</b>   |            |                       |            |                  |       |
| Comment: pr   |            |                       |            |                  |       |
| Corrective Action:  |            |                       |            |                  | Date: |
| Facility ID: 455321   | Type: WELL | API Number: 123-46987 | Status: XX | Insp. Status: ND |       |
| <b>Idle Well</b>  |            |                       |            |                  |       |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: SITE CONDITION |            |                       |            |                  |       |
| Comment: NOT DRILLED<br>Form 2 DOC#: 402341094 expires JUNE 2022  |            |                       |            |                  |       |
| Corrective Action:  |            |                       |            |                  | Date: |
| Facility ID: 455322   | Type: WELL | API Number: 123-46988 | Status: XX | Insp. Status: ND |       |
| <b>Idle Well</b>  |            |                       |            |                  |       |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: SITE CONDITION |            |                       |            |                  |       |
| Comment: NOT DRILLED<br>Form 2 DOC#: 402341129 expires JUNE 2022  |            |                       |            |                  |       |
| Corrective Action:  |            |                       |            |                  | Date: |
| Facility ID: 455323   | Type: WELL | API Number: 123-46989 | Status: XX | Insp. Status: ND |       |
| <b>Idle Well</b>  |            |                       |            |                  |       |
| Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: SITE CONDITION |            |                       |            |                  |       |
| Comment: NOT DRILLED<br>Form 2 DOC: 402341132 expires JUNE 2022   |            |                       |            |                  |       |
| Corrective Action:  |            |                       |            |                  | Date: |
| Facility ID: 455324   | Type: WELL | API Number: 123-46990 | Status: PR | Insp. Status: PR |       |
| <b>Producing Well</b>   |            |                       |            |                  |       |
| Comment: PR   |            |                       |            |                  |       |
| Corrective Action:  |            |                       |            |                  | Date: |
| Facility ID: 455325   | Type: WELL | API Number: 123-46991 | Status: XX | Insp. Status: ND |       |

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: SITE CONDITIONComment: NOT DRILLED

Form 2 DOC#: 402341105 expires JUNE 2022

Corrective Action:

Date:

Facility ID: 455326 Type: WELL API Number: 123-46992 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: SITE CONDITIONComment: NOT DRILLED

Form 2 DOC#: 402341112 expires JUNE 2022

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 | Gravel                  |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <p><b>COGCC Inspection Report Summary</b><br/> <b>**Weather Conditions: sunny, snow</b><br/> On Wednesday, October 28, 2020 at approximately 13:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at ALBERTA CITIES EAST PAD (Enerplus Resources (USA) Corporation), at location #: 455319 in WELD COUNTY Colorado.<br/> While there, I observed a producing facility.<br/> During this inspection the following possible compliance issues were observed:<br/> 1. No labeling is displayed on two tanks. Install sign to comply with Rule 210.d. (Corrective Action Date: December 28, 2020) See attached photo #5.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.<br/> This is a summary of inspection report.</p> | santistb | 10/28/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402523257    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282082">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282082</a> |
| 679603436    | Photos               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282078">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282078</a> |