

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2020

Submitted Date:

12/14/2020

Document Number:

699102860

FIELD INSPECTION FORMLoc ID 459852 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443930	WELL	XX	11/02/2018	LO	123-42417	Guttersen DD17-750	ND
443931	WELL	XX	11/02/2018	LO	123-42418	Guttersen DD17-745	ND
459848	WELL	XX	12/13/2018		123-49065	Guttersen DD17-725	ND
459849	WELL	XX	12/13/2018		123-49066	Guttersen DD17-715	ND
459850	WELL	XX	12/13/2018		123-49067	Guttersen DD17-730	ND
459851	WELL	XX	12/13/2018		123-49068	Guttersen DD17-735	ND

General Comment:

Snow covered ground. Not Drilled wells.

Inspected Facilities

Facility ID: <u>443930</u>	Type: <u>WELL</u>	API Number: <u>123-42417</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>443931</u>	Type: <u>WELL</u>	API Number: <u>123-42418</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459848</u>	Type: <u>WELL</u>	API Number: <u>123-49065</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459849</u>	Type: <u>WELL</u>	API Number: <u>123-49066</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459850</u>	Type: <u>WELL</u>	API Number: <u>123-49067</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459851</u>	Type: <u>WELL</u>	API Number: <u>123-49068</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 12/14/20 at approximately 0856hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Gutteresen DD08-02 Pad of Noble Energy Location ID: 459852 in Weld County, Colorado.</p> <p>While there, I observed a not drilled location.</p> <p>No violation of the COGCC rules were observed at the time of inspection.</p> <p>This is a summary of inspection report.</p>	burnsa	12/14/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102861	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5309613