

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2020

Submitted Date:

12/15/2020

Document Number:

699102896

FIELD INSPECTION FORM

Loc ID 459011 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459012	WELL	XX	11/09/2018		123-48652	Guttersen State DD29-725	ND
459013	WELL	XX	11/09/2018		123-48653	Guttersen State DD29-735	ND
459014	WELL	XX	11/09/2018		123-48654	Guttersen Federal State YY05-735	ND
459015	WELL	XX	11/09/2018		123-48655	Guttersen State DD29-745	ND
459016	WELL	XX	11/09/2018		123-48656	Guttersen Federal State YY05-745	ND
459017	WELL	XX	11/09/2018		123-48657	Guttersen Federal State YY05-725	ND
459018	WELL	XX	11/09/2018		123-48658	Guttersen State DD29-715	ND
459025	WELL	XX	11/09/2018		123-48663	Guttersen Federal State YY05-715	ND

General Comment:

[Snow covered ground. Not drilled "XX"](#)

Inspected Facilities

Facility ID: <u>459012</u>	Type: <u>WELL</u>	API Number: <u>123-48652</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459013</u>	Type: <u>WELL</u>	API Number: <u>123-48653</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459014</u>	Type: <u>WELL</u>	API Number: <u>123-48654</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459015</u>	Type: <u>WELL</u>	API Number: <u>123-48655</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459016</u>	Type: <u>WELL</u>	API Number: <u>123-48656</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459017</u>	Type: <u>WELL</u>	API Number: <u>123-48657</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459018</u>	Type: <u>WELL</u>	API Number: <u>123-48658</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459025</u>	Type: <u>WELL</u>	API Number: <u>123-48663</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 12/15/20 at approximately 1221hrs, I, Inspector Adam Burns, Conducted an on-site inspection at DD 29-15 Pad of Noble Energy Location ID: 459011 in Weld County, Colorado. While there, I observed a not drilled location "XX". No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p>	burnsa	12/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102897	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5310730