

Inspection Photos
Location Name: Horsetail 18-0713H
Location ID: 431632



Photo 1 – Pumping Unit

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Horsetail 18-0713H
Location ID: 431632



Photo 3 – Heater Treater

Photo 4 – Tank Battery

Inspection Photos
Location Name: Horsetail 18-0713H
Location ID: 431632



Photo 5 – ECD and Flare

Photo 6 – Label on Chemical Container has faded

Inspection Photos
Location Name: Horsetail 18-0713H
Location ID: 431632



Photo 7 – Stained Soil at Wellhead

Photo 8 – Stained Soil at Wellhead