



39.78089, -108.62844, 6806.6ft, 334°  
12/22/2020 02:20:49 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Continental 3-16**

**API: 05-103-08578**

**Inspection: 700404722**





39.78074, -108.62811, 6834.9ft, 308°  
12/22/2020 02:23:45 PM



39.78093, -108.62846, 6822.0ft, 174°  
12/22/2020 02:21:33 PM





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Casing gage.**

**Continental 3-16**

**API: 05-103-08578**

**Inspection: 700404722**

365 SOUTH MAIN  
BRIGHTON, CO  
80601  
303-637-0150 www.impactanalytical.com

2020 DEC 22  
OC # 1831

31 Operating

Station Name Continental 3-16  
Station No. 93481 Producer Continental  
Sec 16 Township 35 Range 100  
Diff 0-100 Temp Range 0-150 Tube Size 2.067  
Static 0-250 Absolute 11.4 PSI

Date	Orifice Plate Size	Meter Test Date	Sample Date
4.15.9	2x .375	4.15.9	4.15.9
6.23.10	.375	6.23.10	6.23.10
7.22.11	.375	7.22.11	7.22.11
6.28.12	0.375	6.28.12	6.28.12
6.6.13	0.375	6.6.13	6.6.13
8.13.14	0.375	8.13.14	8.13.14
6.9.15	0.375	6.9.15	
6.7.16	0.375	6.7.16	
6.8.17	0.375	6.8.16	

EMPACT Analytical Systems Inc.  
303-637-0150

39.78081, -108.62811, 6835.6ft, 314°  
12/22/2020 02:24:07 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 5. Meter calibration card.

Continental 3-16

API: 05-103-08578

Inspection: 700404722