



39.87659, -108.65948, 6401.2ft, 60°  
12/23/2020 01:54:33 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Shenandoah 6-18**

**API: 05-103-08718**

**Inspection: 700404771**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well gas leaks.**

**Shenandoah 6-18**

**API: 05-103-08718**

**Inspection: 700404771**



39.87687, -108.65889, 6400.9ft, 11°  
12/23/2020 01:53:11 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 4. Tubing gage.**

**Shenandoah 6-18**

**API: 05-103-08718**

**Inspection: 700404771**



39.87655, -108.65917, 6391.5ft, 327°  
12/23/2020 01:55:06 PM



39.87689, -108.65896, 6392.7ft, 328°  
12/23/2020 01:53:28 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Pit.**

**Shenandoah 6-18**

**API: 05-103-08718**

**Inspection: 700404771**

[illegible][illegible]

## ANALYSIS

[illegible]

39.87663, -108.65926, 6405.8ft, 296°  
12/23/2020 01:55:51 PM