

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/09/2021

Submitted Date:

02/10/2021

Document Number:

699103160

FIELD INSPECTION FORM

Loc ID 459457 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459454	WELL	XX	11/30/2018		123-48864	Gittlein C22-755	ND
459455	WELL	XX	11/30/2018		123-48865	Gittlein D10-770	ND
459456	WELL	XX	11/30/2018		123-48866	Gittlein C22-750	ND
459458	WELL	XX	11/30/2018		123-48867	Gittlein C22-775	ND
459459	WELL	XX	11/30/2018		123-48868	Gittlein D10-785	ND
459460	WELL	XX	11/30/2018		123-48869	Gittlein D10-755	ND
459461	WELL	XX	11/30/2018		123-48870	Gittlein D10-765	ND
459463	WELL	XX	11/30/2018		123-48871	Gittlein D10-775	ND
459464	WELL	XX	11/30/2018		123-48872	Gittlein C22-765	ND
459465	WELL	XX	11/30/2018		123-48873	Gittlein C22-785	ND
459890	WELL	XX	12/13/2018		123-49096	Gittlein C22-770	ND

General Comment:

no oil and gas activity.
Form 2A #401799822 Exp. Date of 10/28/2024

Inspected Facilities

Facility ID: <u>459454</u>	Type: <u>WELL</u>	API Number: <u>123-48864</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459455</u>	Type: <u>WELL</u>	API Number: <u>123-48865</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459456</u>	Type: <u>WELL</u>	API Number: <u>123-48866</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459458</u>	Type: <u>WELL</u>	API Number: <u>123-48867</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459459</u>	Type: <u>WELL</u>	API Number: <u>123-48868</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459460</u>	Type: <u>WELL</u>	API Number: <u>123-48869</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459461</u>	Type: <u>WELL</u>	API Number: <u>123-48870</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459463</u>	Type: <u>WELL</u>	API Number: <u>123-48871</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459464</u>	Type: <u>WELL</u>	API Number: <u>123-48872</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459465</u>	Type: <u>WELL</u>	API Number: <u>123-48873</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>
Facility ID: <u>459890</u>	Type: <u>WELL</u>	API Number: <u>123-49096</u>	Status: <u>XX</u>	Insp. Status: <u>ND</u>

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 2/9/21 at approximately 0747hrs, I, Inspector Adam Burns, Conducted an on-site inspection at C34-14 Multi Well of Noble Energy Location ID: 459457 in Weld County, Colorado. While there, I observed a well pad that is not drilled. Appears to have no oil and gas activity. Form 2A #401799822 Exp. Date of 10/28/2024 No violation of the COGCC rules were observed at the time of inspection. This is a summary of inspection report.</p>	burnsa	02/10/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103161	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5349348